

KMC 4/4  
B/21/7



Government of West Bengal  
Irrigation & Waterways Directorate  
Office of the Executive Engineer  
Metropolitan Drainage Division No. II  
Jalasampad Bhawan, 7<sup>th</sup> floor  
Salt Lake City, Kolkata-700091

Phone No. : 033 23597459/551

Fax No. : 033 23597459

E-mail ID:

eemdd921@gmail.com

Memo No. 1249/7-230

Dated: 31/07/19

To  
The Superintending Engineer  
Metropolitan Drainage Circle  
Jalasampad Bhawan, 2<sup>nd</sup> floor.  
Salt Lake City, Kolkata-700091

Sub: Joint Inspection Report of TP Khal in front of Urbana Housing Complex, Anandapur, Kol-700107.

Sir,

As per your verbal instruction, a joint visit has been done with the representative of Urbana Housing Complex, Executive Engineer (S&W) of KMC, Assistant Engineer-II of MDD-II and me, held on 30.07.19. The problems and solutions are found as follows:

**Regarding Irrigation Department:**

1.	Problem	Unhygienic condition/accumulation of floating garbage at the barrier in front of the Complex.
	Solution	Garbage can be cleaned twice in a week at least during monsoon period. Presently, the cleaning of the garbage is done once in a week.
2.	Problem	Deposition of ash (burnt residual garbage) near the barrier.
	Solution	The solid burnt residual garbage will be disposed off from the canal side shortly as per request.
3.	Problem	Fencing, lining and beautification of canal near the said location.
	Solution	Proposal is needed for a permanent nature of job and can be done when fund will be available.

**Regarding Housing:**

1.	Problem	There are so many temporary shops near Urbana Housing who dump their solid waste to the canal. Thus, an aesthetic of the canal worsen.
	Solution	The member of the housing agreed to make suitable awareness programme among the shops and will distribute bins so that the garbage can not be litre.

**Regarding KMC**

1.	Problem	A surface drain named Madurdaha Khal flowing along the Housing Complex is fully choked. It has become a breeding ground of vector born diseases.
	Solution	KMC Official has to clean the surface drain immediately.
2.	Problem	Illegal encroachment over drain in both side of road in between EM By-pass and TP Khal. The drain is silted up and unable to carry surface discharge as reported by the Housing Complex.
	Solution	Action to be taken from the KMC Official.

This is for your kind information and favour of necessary action please.

Yours faithfully,

Executive Engineer

Metropolitan Drainage Divn.No.II

Dated:

Memo No.

Copy for information and necessary action to The Assistant Engineer-II, MDD-II.

Executive Engineer

Metropolitan Drainage Divn.No.II